



Solder jumpers are normally open. Add jumpers if pullups are needed.

